



RESTORATION PROJECT AT BUFFALO BY
WWW.ASIANSTONES.COM

The Building



Some Before and After pictures with new replicated stones to replace the old broken and worn out pieces with corresponding CAD Drawings

Before



After


Niche Sill

Before




After

Niche Sill Drawing



Mullion and Sill

Before





www.asianstones.com



After

Mullion and Sill Drawing



Dentils

Before




www.asianstones.com




After

Dentil Drawing



Quoins and Window Lintels

Before





www.asianstones.com



After

Quoin and Lintel Drawing



Brackets and Lintels

Before




www.asianstones.com




After

Bracket Drawing



Keystones



Keystone Drawing

